Viewpro

F Series Gimbal Camera
## Change Frame Rate to 720p

1. Connect **USB to TTL** cable with gimbal and PC

Connection method:

Black wire GND -------- Gimbal GND

Green wire TX ---------- TX silk printed on the gimbal controller Z-3D

White wire RX ----------- RX silk printed on the gimbal controller Z-3D

2. Power on the gimbal, open softare **VideoInConsole**

1> Finish basic settings on the software as below showing: choose correct COM number (you can check in your PC manager). Baudrate: default is 115200. Data bit: 8, no checksum. Stop bit: 1.

2> Port status: 打开 (Open)

3. Choose module protocol **"PelcoD 协议"**

4. Click on **"+"** under **"变倍"(Zoom),** the image zoom in. (Communication is normal)

5. Click on **"模式切换" (Change mode)**

6. Click on **"菜单"(Menu)**

Screen will show menu as below:

7. Click **"右"(Right)** first, then **"下" (Down)** to reach **"HDMI 输出"** of the menu on the screen.

![Viewpro logo]

8. Clink on **"设置" (Set),** and then click **"右" (Right)**. Choose **"720P"**

9. Click on **"设置" (Set)** again. The screen will show **720P** as below.

10. Click on **"菜单"(Menu)**, quit out. Setting is done.